



## FRAISES ROTATIVES → *Type FME*



Modèle	A (mm)	A1 (mm)	A2 (mm)	B (mm)	C (mm)
<b>FME090</b>	870	435	435	50	50
<b>FME100</b>	1020	435	585	180	50
<b>FME120</b>	1210	430	780	180	50

## FRAISES ROTATIVES → *Type FMS*



Modèle	A (mm)	A1 (mm)	A2 (mm)	B (mm)	C (mm)
<b>FMS100</b>	1000	500	500	105	105
<b>FMS120</b>	1200	600	600	165	165
<b>FMS140</b>	1400	700	700	165	165